

HLH

Material Guide

Vacuum Casting

Vacuum Casting Materials

Type	Material Reference		Material	
Plastic	Similar to ABS		DPI 8150	
			PX5118	
	High temperature resistant ABS	70 °C	Hei-cast 8150	
		150 °C	PX223HT	
		150 °C	6160	
	Soft Rubber	Adjustable color		8400
		Transparent soft adhesive		T-0387
		Similar to ABS		8263
		Similar to ABS		MU55
	Transparent material	Similar to PC (With blue color)		PX 520
		Similar to PP		5690
		Similar to PMMA		1819